Dane aktualne na dzień: 21-11-2026 13:55

Link do produktu: https://inforolnik.pl/lampa-tylna-lewostronny-cobo-landini-massey-ferguson-02368000-02396000-1678868m91-1678868m92-1808843m92-1668657m91-1678868v92-1808843m91-p-9435.html



Lampa tylna (Lewostronny) Cobo Landini Massey Ferguson 02.368.000 02.396.000 1678868M91 1678868M92 1808843M92 1668657M91 1678868V92 1808843M91

Cena w sklepie online	**128,00 zł**
Czas wysyłki	**2-3 dni**
Numer katalogowy	**S.41127**

Opis produktu

Z zatwierdzeniem E Wysokość: 73mm, Szerokość: 180mm, Głębokość: 70mm, Napięcie: 12V, Wymienna żarówka: Stop/Z bocznym zaworem 12V 21/5W S.110010, Wskaźnik świateł awaryjnych 12V/21W S.109961, Wymienne klosze: Numery porównawcze: 02.368.000 02.396.000 1678868M91 1678868M92 1808843M92 1668657M91 1678868V92 1808843M91

Zastosowanie

Kliknij i zobacz inne części które również pasują do : Landini 5830 (30 Series)Landini 6030 (30 Series)Landini 6530 (30 Series) Landini 8530 (30 Series)Massey Ferguson 174 (100 Italian Series)Massey Ferguson 194 (100 Italian Series)Massey Ferguson 230 (200 Series)Massey Ferguson 240 (200 Series)Massey Ferguson 250 (200 Series)Massey Ferguson 253 (200 Series) Massey Ferguson 263 (200 Series)Massey Ferguson 265 (200 Series)Massey Ferguson 275 (200 Series)Massey Ferguson 290 (200 Series)Massey Ferguson 298 (200 Series)Massey Ferguson 340 (300 Series)Massey Ferguson 374 (300 Italian Series) Massey Ferguson 375E BRAZILIANMassey Ferguson 390E BRAZILIANMassey Ferguson 394 (300 Italian Series)Massey Ferguson 550 (500 Series)Massey Ferguson 565 (500 Series)Massey Ferguson 575 (500 Series)Massey Ferguson 590 (500 Series)