Dane aktualne na dzień: 18-11-2026 12:02

Link do produktu: https://inforolnik.pl/uszczelka-pod-kolektor-landini-massey-ferguson-1876671m2-3539379m1-1876671m4-1876671v2-3539379v1-p-21705.html




# Uszczelka pod kolektor Landini Massey Ferguson 1876671M2 3539379M1 1876671M4 1876671V2 3539379V1

| | |
|---|---|
| Cena w sklepie online | **5,52 zł** |
| Czas wysyłki | **2-3 dni** |
| Numer katalogowy | **S.42646** |

## Opis produktu

Ref.1876671M2 Numery porównawcze: 1876671M2 3539379M1 1876671M4 1876671V2 3539379V1

## Zastosowanie

Kliknij i zobacz inne części które również pasują do : Landini 6550 (50 Series)Landini 6880 (80 Series)Landini 7550 (50 Series) Landini 7830 (30 Series)Landini 7880 (80 Series)Landini 8550 (50 Series)Landini 8880 (80 Series)Massey Ferguson 260 (200 Series)Massey Ferguson 265 BRAZILIANMassey Ferguson 275 BRAZILIANMassey Ferguson 283 BRAZILIANMassey Ferguson 290 BRAZILIANMassey Ferguson 375E BRAZILIANMassey Ferguson 390E BRAZILIANMassey Ferguson 425 BRAZILIANMassey Ferguson 435 BRAZILIANMassey Ferguson 440 BRAZILIANMassey Ferguson 445 BRAZILIAN