

Link do produktu: <https://inforolnik.pl/alternator-mahle-14v-65-amper-agco-bosch-claas-fiat-ford-new-holland-iskra-iveco-lester-lucas-same-72277319-120489152-120489219-6005712872-39525-p-10568.html>



Alternator (Mahle) - 14V, 65 Amper AGCO Bosch Claas Fiat Ford New Holland Iskra IVECO Lester Lucas Same 72277319 120489152 120489219 6005712872 39525

Cena w sklepie online **696,00 zł**

Czas wysyłki **2-3 dni**

Numer katalogowy **S.35924**

Opis produktu

Numery porównawcze: 72277319 120489152 120489219 6005712872 395250A1 47906830 47906837 84296693 84296707 84402416 84402417 84402418 84402419 84522025 99457034 99478834 84297514 IA0463 99457074 99461495 12281 12581 12583 20750 LRA01915 294393200 294393700 294395500

Zastosowanie

Kliknij i zobacz inne części które również pasują do : [Deutz-Fahr AGROCLIMBER 320](#)[Deutz-Fahr AGROCLIMBER 400](#)[Deutz-Fahr AGROCLIMBER 410](#)[Deutz-Fahr AGROLUX 310](#)[Deutz-Fahr AGROLUX 320](#)[Deutz-Fahr AGROLUX 410](#)[Deutz-Fahr AGROLUX 57](#)[Deutz-Fahr AGROLUX 65](#)[Deutz-Fahr AGROLUX 67](#)[Deutz-Fahr AGROLUX 75](#)[Deutz-Fahr Agroplus 100 \(Agroplus Series\)](#)[Deutz-Fahr AGROPLUS 310](#)[Deutz-Fahr AGROPLUS 315](#)[Deutz-Fahr AGROPLUS 330](#)[Deutz-Fahr AGROPLUS 410](#)[Deutz-Fahr AGROPLUS 420](#)[Deutz-Fahr AGROPLUS 430](#)[Deutz-Fahr Agroplus 60 \(Agroplus Series\)](#)[Deutz-Fahr Agroplus 70 \(Agroplus Series\)](#)[Deutz-Fahr Agroplus 75 \(Agroplus Series\)](#)[Deutz-Fahr Agroplus 85 \(Agroplus Series\)](#)[Deutz-Fahr Agroplus 95 \(Agroplus Series\)](#)[Deutz-Fahr AGROPLUS F 405 ECOLINE](#)[Fiat L60 \(L Series\)](#)[Fiat L65 \(L Series\)](#)[Fiat L85 \(L Series\)](#)[Fiat L95 \(L Series\)](#)[Ford New Holland 4635 \(35 Series \)](#)[Ford New Holland 4835 \(35 Series \)](#)[Ford New Holland 5635 \(35 Series \)](#)[Ford New Holland 6635 \(35 Series \)](#)[Ford New Holland 7635 \(35 Series \)](#)[Ford New Holland TL100 \(TL Series\)](#)[Ford New Holland TL70 \(TL Series\)](#)[Ford New Holland TL80 \(TL Series\)](#)[Ford New Holland TL90 \(TL Series\)](#)[Hurlimann 355](#)[Hurlimann 358](#)[Hurlimann 360](#)[Hurlimann 468-70](#)[Hurlimann 468](#)[CLAB Hurlimann 470](#)[Hurlimann 478-80](#)[Hurlimann 480](#)[Hurlimann 488](#)[Hurlimann 488-90](#)[Hurlimann 490](#)[Hurlimann 5110](#)[Hurlimann 5116](#)[Hurlimann 5116TH](#)[Hurlimann 6115](#)[Hurlimann 6130](#)[Hurlimann 6135](#)[Hurlimann 6136](#)[Hurlimann 6160](#)[Hurlimann 6170](#)[Lamborghini 1106 \(Various Series\)](#)[Lamborghini 115 FORMULA](#)[Lamborghini 1306 \(Various Series\)](#)[Lamborghini 135 FORMULA](#)[Lamborghini 1506 \(Various Series\)](#)[Lamborghini 1556 \(Various Series\)](#)[Lamborghini 165 RACING](#)[Lamborghini 1706 \(Various Series\)](#)[Lamborghini 190 RACING](#)[Lamborghini 674/70](#)[Lamborghini 674/70N](#)[Lamborghini 674/70N BASSO](#)[Lamborghini 674-70 \(Various Series\)](#)[Lamborghini 774 \(Various Series\)](#)[Lamborghini 774/80](#)[Lamborghini 774/80DT](#)[Lamborghini 774/80NL](#)[Lamborghini 774-80 \(Various Series\)](#)[Lamborghini 874.9](#)[Lamborghini 874-90 \(Various Series\)](#)[Lamborghini 874TL](#)[Lamborghini 956 \(Various Series\)](#)[Lamborghini R874-90](#)[Lamborghini R956-100](#)[Same Antares 100 \(Antares\)](#)[Same Antares 130 \(Antares\)](#)[Same ANTARES 150](#)[Same Argon 50 \(Argon\)](#)[Same Argon 60 \(Argon\)](#)[Same Argon 70 \(Argon\)](#)[Same ARGON 75](#)[Same ARGON 80](#)[Same Aster 60 \(Aster\)](#)[Same Centauro 70 \(Centauro\)](#)[Same Centauro 75 \(Centauro\)](#)[Same Centurion 70 \(Centurion\)](#)[Same Centurion 75 \(Centurion\)](#)[Same Delfino 30 \(Delfino\)](#)[Same Delfino 32 \(Delfino\)](#)[Same Delfino 35 \(Delfino\)](#)[Same Dorado 100 \(Dorado\)](#)[Same Dorado 60 \(Dorado\)](#)[Same Dorado 70 \(Dorado\)](#)[Same DORADO 90](#)[Same Drago 120 \(Drago\)](#)[Same Drago 65 \(Drago\)](#)[Same Drago 75 \(Drago\)](#)[Same Drago 85 \(Drago\)](#)[Same Explorer 55 \(Explorer\)](#)[Same Explorer 60 \(Explorer\)](#)[Same Explorer 65 \(Explorer\)](#)[Same Explorer 70 \(Explorer\)](#)[Same Explorer 75 \(Explorer\)](#)[Same Explorer 80 \(Explorer\)](#)[Same Explorer 85 \(Explorer\)](#)[Same Explorer 90 \(Explorer\)](#)[Same Explorer II 70 \(Explorer\)](#)[Same Explorer II 80 \(Explorer\)](#)[Same FRUTTETO 100](#)[Same FRUTTETO 110](#)[Same Frutteto 60 \(Frutteto\)](#)[Same Frutteto 75 \(Frutteto\)](#)[Same FRUTTETO 80.4](#)[Same Frutteto 85 \(Frutteto\)](#)[Same FRUTTETO 90](#)[Same Galaxy 170 \(Galaxy\)](#)[Same Golden 60 \(Golden\)](#)[Same Golden 65 \(Golden\)](#)[Same Golden 75 \(Golden\)](#)[Same Golden 85 \(Golden\)](#)[Same](#)

Account for EURO PAYMENTS:

PL78 1140 2004 0000 3812 0242 0461

Bic (IBAN) : BREXPLPWMBK

[Hercules 160 \(Hercules\)](#)[Same Jaguar 100 \(Jaguar\)](#)[Same Jaguar 95 \(Jaguar\)](#)[Same Krypton 100 \(Krypton\)](#)[Same KRYPTON 110](#)[Same Krypton 90 \(Krypton\)](#)[Same Laser 100 \(Laser\)](#)[Same Laser 110 \(Laser\)](#)[Same Laser 130 \(Laser\)](#)[Same Laser 150 \(Laser\)](#)[Same LASER 85](#)[Same Laser 90 \(Laser\)](#)[Same Leopard 85 \(Leopard\)](#)[Same Leopard 90 \(Leopard\)](#)[Same Mercury 85 \(Mercury\)](#)[Same Minitauro 60 \(Minitauro\)](#)[Same Panther 95 \(Panther\)](#)[Same Ranger 45 \(Ranger\)](#)[Same Silver 100.4 \(Silver\)](#)[Same Silver 100.6 \(Silver\)](#)[Same Silver 105 \(Silver\)](#)[Same Silver 110 \(Silver\)](#)[Same Silver 80 \(Silver\)](#)[Same Silver 85 \(Silver\)](#)[Same Silver 90 \(Silver\)](#)[Same Silver 95 \(Silver\)](#)[Same Solar 50 \(Solar\)](#)[Same SOLAR 55](#)[Same Solar 60 \(Solar\)](#)[Same Taurus 60 \(Taurus\)](#)[Same Tiger Six 105 \(Tiger\)](#)[Same Titan 160 \(Titan\)](#)[Same Trident 130 \(Trident\)](#)[Same Vigneron 20 \(Vigneron\)](#)[Same Vigneron 60 \(Vigneron\)](#)[Same Vigneron 62 \(Vigneron\)](#)[Same Vigneron 70 \(Vigneron\)](#)[Same Vigneron 75 \(Vigneron\)](#)