

Link do produktu: <https://inforolnik.pl/pierscien-uszczelniajacy-135-x-114-x-12mm-fiat-ford-new-holland-1930330-4000380-40101341-4754029-4781935-98461686-99457401-1930331-1930332-504127327-p-23695.html>



Pierścień uszczelniający 135 x 114 x 12mm Fiat Ford New Holland 1930330 4000380 40101341 4754029 4781935 98461686 99457401 1930331 1930332 504127327

Cena w sklepie online **71,00 zł**

Czas wysyłki **2-3 dni**

Numer katalogowy **S.62073**

Opis produktu

Numery porównawcze: 1930330 4000380 40101341 4754029 4781935 98461686 99457401 1930331 1930332 504127327 98461694 98488322 98488392 98489586

Zastosowanie

Kliknij i zobacz inne części które również pasują do : [Case IH 55JXMC](#)[Case IH 65JXMC](#)[Case IH 75JXMC](#)[Case IH 80JXMC](#)[Case IH 90JXMC](#)[Case IH AVJ55 \(AVJ Series\)](#)[Case IH AVJ60 \(AVJ Series\)](#)[Case IH AVJ70 \(AVJ Series\)](#)[Case IH JX100UC](#)[Case IH JX1060C](#)[Case IH JX1060V](#)[Case IH JX1070C](#)[Case IH JX1070N](#)[Case IH JX1070V](#)[Case IH JX1075C](#)[Case IH JX1075N](#)[Case IH JX1075V](#)[Case IH JX1095N](#)[Case IH JX1095V](#)[Case IH JX55 \(JX Series\)](#)[Case IH JX55T](#)[Case IH JX60 \(JX Series\)](#)[Case IH JX65 \(JX Series\)](#)[Case IH JX70 \(JX Series\)](#)[Case IH JX70UC](#)[Case IH JX75 \(JX Series\)](#)[Case IH JX75T](#)[Case IH JX80 \(JX Series\)](#)[Case IH JX80UC](#)[Case IH JX85 \(JX Series\)](#)[Case IH JX90 \(JX Series\)](#)[Case IH JX90UC](#)[Case IH JX95 \(JX Series\)](#)[Case IH VJ60 \(VJ Series\)](#)[Case IH VJ70 \(VJ Series\)](#)[Case IH VJ80 \(VJ Series\)](#)[Fiat 100-90 \(90 Series\)](#)[Fiat 110-90 \(90 Series\)](#)[Fiat 115-90 \(90 Series\)](#)[Fiat 130-90 \(90 Series\)](#)[Fiat 140-90 \(90 Series\)](#)[Fiat 446 \(Classic Models\)](#)[Fiat 45-66 \(66 Series\)](#)[Fiat 466 \(Classic Models\)](#)[Fiat 50-66 \(66 Series\)](#)[Fiat 55-66 \(66 Series\)](#)[Fiat 55-76 \(76 Series\)](#)[Fiat 55-90 \(90 Series\)](#)[Fiat 566 \(Classic Models\)](#)[Fiat 60-66 \(66 Series\)](#)[Fiat 60-76 \(76 Series\)](#)[Fiat 60-90 \(90 Series\)](#)[Fiat 60-93 \(93 Series\)](#)[Fiat 60-94 \(94 Series\)](#)[Fiat 65-66 \(66 Series\)](#)[Fiat 65-90 \(90 Series\)](#)[Fiat 65-93 \(93 Series\)](#)[Fiat 65-94 \(94 Series\)](#)[Fiat 666 \(Classic Models\)](#)[Fiat 70-66 \(66 Series\)](#)[Fiat 70-76 \(76 Series\)](#)[Fiat 70-90 \(90 Series\)](#)[Fiat 72-93 \(93 Series\)](#)[Fiat 72-94 \(94 Series\)](#)[Fiat 766 \(Classic Models\)](#)[Fiat 80-66 \(66 Series\)](#)[Fiat 80-76 \(76 Series\)](#)[Fiat 80-90 \(90 Series\)](#)[Fiat 82-93 \(93 Series\)](#)[Fiat 82-94 \(94 Series\)](#)[Fiat 85-90 \(90 Series\)](#)[Fiat 90-90 \(90 Series\)](#)[Fiat F100 \(F Series\)](#)[Fiat F110 \(F Series\)](#)[Fiat F115 \(F Series\)](#)[Fiat F120 \(F Series\)](#)[Fiat F130 \(F Series\)](#)[Fiat F140 \(F Series\)](#)[Fiat L60 \(L Series\)](#)[Fiat L65 \(L Series\)](#)[Fiat L75 \(L Series\)](#)[Fiat L85 \(L Series\)](#)[Fiat L95 \(L Series\)](#)[Ford New Holland 3010S](#)[Ford New Holland 3435 \(35 Series\)](#)[Ford New Holland 3830 \(30 Series\)](#)[Ford New Holland 3935 \(35 Series\)](#)[Ford New Holland 4010S](#)[Ford New Holland 4135 \(35 Series\)](#)[Ford New Holland 4230 \(30 Series\)](#)[Ford New Holland 4330 \(30 Series\)](#)[Ford New Holland 4430 \(30 Series\)](#)[Ford New Holland 4635 \(35 Series\)](#)[Ford New Holland 4835 \(35 Series\)](#)[Ford New Holland 5010S](#)[Ford New Holland 5635 \(35 Series\)](#)[Ford New Holland 6635 \(35 Series\)](#)[Ford New Holland 7635 \(35 Series\)](#)[Ford New Holland TD55D](#)[Ford New Holland TD60 \(TD Series\)](#)[Ford New Holland TD60D](#)[Ford New Holland TD65B](#)[Ford New Holland TD65D](#)[Ford New Holland TD65F](#)[Ford New Holland TD70 \(TD Series\)](#)[Ford New Holland TD70D](#)[Ford New Holland TD75D](#)[Ford New Holland TD75F](#)[Ford New Holland TD80 \(TD Series\)](#)[Ford New Holland TD80D](#)[Ford New Holland TD85D](#)[Ford New Holland TD85F](#)[Ford New Holland TD90 \(TD Series\)](#)[Ford New Holland TD90D](#)[Ford New Holland TD95 \(TD Series\)](#)[Ford New Holland TD95D](#)[Ford New Holland TL100 \(TL Series\)](#)[Ford New Holland TL65 \(TL Series\)](#)[Ford New Holland TL70 \(TL Series\)](#)[Ford New Holland TL80 \(TL Series\)](#)[Ford New Holland TL90 \(TL Series\)](#)[Ford New Holland TN55 \(TN Series\)](#)[Ford New Holland TN55V](#)[Ford New Holland TN65 \(TN Series\)](#)[Ford New Holland TN65F](#)[Ford New Holland TN65V](#)[Ford New Holland TN70 \(TN Series\)](#)[Ford New Holland TN70F](#)[Ford New Holland TN75 \(TN Series\)](#)[Ford New Holland TN75F](#)[Ford New Holland TN75V](#)[Ford New Holland TN80F](#)[Ford New Holland TN90F](#)[Ford New Holland TT50](#)[Ford New Holland TT55](#)[Ford New Holland TT65](#)[Ford New Holland TT65D](#)[Ford New Holland TT75](#)[Steyr 360 KOMPAKT](#)[Steyr 370 KOMPAKT](#)[Steyr 375 KOMPAKT](#)[White Oliver 1365](#)[White Oliver 1370](#)[White](#)

Account for EURO PAYMENTS:

PL78 1140 2004 0000 3812 0242 0461

Bic (IBAN) : BREXPLPWMBK

[Oliver 2-60White Oliver 700](#)