

Link do produktu: <https://inforolnik.pl/pompa-paliwowa-case-ih-ford-new-holland-2830122-2830266-504146090-504380241-84268475-84269570-4892387-6905143-84268745-p-22957.html>



Pompa paliwowa Case IH Ford New Holland 2830122 2830266 504146090 504380241 84268475 84269570 4892387 6905143 84268745

Cena w sklepie online **144,00 zł**

Czas wysyłki **2-3 dni**

Numer katalogowy **S.118466**

Opis produktu

Numery porównawcze: 2830122 2830266 504146090 504380241 84268475 84269570 4892387 6905143 84268745

Zastosowanie

Kliknij i zobacz inne części które również pasują do : [Case IH FARMALL 110A](#)[Case IH FARMALL 120A](#)[Case IH FARMALL 55C](#)[Case IH FARMALL 65C](#)[Case IH FARMALL 75C](#)[Case IH JX1070U](#)[Case IH JX1080U](#)[Case IH JX1085C](#)[Case IH JX1090U](#)[Case IH JX1095C](#)[Case IH JX1100U](#)[Case IH JX60 \(JX Series\)](#)[Case IH JX70 \(JX Series\)](#)[Case IH JX75U](#)[Case IH JX80 \(JX Series\)](#)[Case IH JX85U](#)[Case IH JX90 \(JX Series\)](#)[Case IH JX95 \(JX Series\)](#)[Case IH JX95U](#)[Case IH JXU 105](#)[Case IH JXU 115](#)[Case IH JXU 75](#)[Case IH JXU 85](#)[Case IH JXU 95](#)[Case IH Maxxum 100 \(Maxxum Series\)](#)[Case IH Maxxum 110 \(Maxxum Series\)](#)[Case IH Maxxum 115 \(Maxxum Series\)](#)[Case IH Maxxum 125 \(Maxxum Series\)](#)[Case IH MAXXUM 140](#)[Case IH MAXXUM 145](#)[Case IH MXU100 \(MXU Series\)](#)[Case IH MXU110 \(MXU Series\)](#)[Case IH MXU115 \(MXU Series\)](#)[Case IH MXU130 \(MXU Series\)](#)[Case IH QUANTUM 65C](#)[Case IH QUANTUM 65V](#)[Case IH QUANTUM 75C](#)[Case IH QUANTUM 75F](#)[Case IH QUANTUM 75N](#)[Case IH QUANTUM 75V](#)[Case IH QUANTUM 85C](#)[Case IH QUANTUM 85F](#)[Case IH QUANTUM 85N](#)[Case IH QUANTUM 85V](#)[Case IH QUANTUM 95C](#)[Case IH QUANTUM 95F](#)[Case IH QUANTUM 95N](#)[Case IH QUANTUM 95V](#)[Ford New Holland 5610S](#)[Ford New Holland 6610S](#)[Ford New Holland 7610S](#)[Ford New Holland 7630](#)[Ford New Holland 8030 \(Combines - Clayton\)](#)[Ford New Holland 8610S](#)[Ford New Holland LM415A](#)[Ford New Holland LM425A](#)[Ford New Holland LM435A](#)[Ford New Holland LM445A](#)[Ford New Holland T4.105](#)[Ford New Holland T4.105F](#)[Ford New Holland T4.105V](#)[Ford New Holland T4.55](#)[Ford New Holland T4.65](#)[Ford New Holland T4.65V](#)[Ford New Holland T4.75](#)[Ford New Holland T4.75F](#)[Ford New Holland T4.75LP](#)[Ford New Holland T4.75V](#)[Ford New Holland T4.85](#)[Ford New Holland T4.85F](#)[Ford New Holland T4.85LP](#)[Ford New Holland T4.85V](#)[Ford New Holland T4.95](#)[Ford New Holland T4.95F](#)[Ford New Holland T4.95LP](#)[Ford New Holland T4.95V](#)[Ford New Holland T4020](#)[Ford New Holland T4020F](#)[Ford New Holland T4020V](#)[Ford New Holland T4030](#)[Ford New Holland T4030F](#)[Ford New Holland T4030V](#)[Ford New Holland T4040](#)[Ford New Holland T4040F](#)[Ford New Holland T4040V](#)[Ford New Holland T4050](#)[Ford New Holland T4050F](#)[Ford New Holland T4050V](#)[Ford New Holland T4060](#)[Ford New Holland T4060V](#)[Ford New Holland T5030 \(T5000 Series\)](#)[Ford New Holland T5040 \(T5000 Series\)](#)[Ford New Holland T5050 \(T5000 Series\)](#)[Ford New Holland T5060 \(T5000 Series\)](#)[Ford New Holland T5070 \(T5000 Series\)](#)[Ford New Holland T6010 \(T6000 Series\)](#)[Ford New Holland T6020 \(T6000 Series\)](#)[Ford New Holland T6030 \(T6000 Series\)](#)[Ford New Holland T6050 \(T6000 Series\)](#)[Ford New Holland T6070 \(T6000 Series\)](#)[Ford New Holland TD4020](#)[Ford New Holland TD4030](#)[Ford New Holland TD4040](#)[Ford New Holland TD5.105](#)[Ford New Holland TD5.85](#)[Ford New Holland TD5.95](#)[Ford New Holland TD5010](#)[Ford New Holland TD5020](#)[Ford New Holland TD5030](#)[Ford New Holland TD5040](#)[Ford New Holland TD5050](#)[Ford New Holland TK4020](#)[Ford New Holland TK4030 \(TK Series - Crawlers\)](#)[Ford New Holland TK4040](#)[Ford New Holland TK4050](#)[Ford New Holland TK4060](#)[Ford New Holland TL100A](#)[Ford New Holland TL70A](#)[Ford New Holland TL80A](#)[Ford New Holland TL90A](#)[Ford New Holland TM7010](#)[Ford New Holland TM7010 BRAZILIAN](#)[Ford New Holland TM7020](#)[Ford New Holland TM7020 BRAZILIAN](#)[Ford New Holland TM7030](#)[Ford New Holland TM7030 BRAZILIAN](#)[Ford New Holland TM7040](#)[Ford New Holland TM7040 BRAZILIAN](#)[Ford New Holland TN85A](#)[Ford New Holland TN85DA](#)[Ford New Holland TN85SA](#)[Ford New Holland TN95A](#)[Ford New Holland TN95DA](#)[Ford New Holland TS100A](#)[Ford New Holland TS110A](#)[Ford New Holland TS115A](#)[Ford New](#)

Account for EURO PAYMENTS:

PL78 1140 2004 0000 3812 0242 0461

Bic (IBAN) : BREXPLPWMBK

[Holland TS125A](#)[Ford New Holland TS130A](#)[Ford New Holland TS6.110 BRAZILIAN](#)[Ford New Holland TS6.120 BRAZILIAN](#)[Ford New Holland TS6000 BRAZILIAN](#)[Ford New Holland TS6020](#)[Ford New Holland TS6020 BRAZILIAN](#)[Ford New Holland TS6030](#)[Ford New Holland TS6030 BRAZILIAN](#)[Ford New Holland TS6040 BRAZILIAN](#)[Steyr 4055S KOMPAKT](#)[Steyr 4065 KOMPAKT](#)[Steyr 4065S KOMPAKT](#)[Steyr 4075 KOMPAKT](#)[Steyr 4085 KOMPAKT](#)[Steyr 4095 KOMPAKT](#)[Steyr 4100 Profi \(Profi Series\)](#)[Steyr 4110 PROF](#)[Steyr 485 KOMPAKT](#)[Steyr 495 KOMPAKT](#)[Steyr 6115 Profi \(Profi Series\)](#)[Steyr 6125 Profi \(Profi Series\)](#)[Steyr 6140 PROF](#)